

Attached is a chart showing BOP pressure over time, from when the acoustic transmitter has been operating. The pressures from the transmitter below the BOP test rams have been calibrated against the gauges we installed for the Top Kill and have a correction factor of 966 psi already applied. A number of points can be taken from the graphs, including:

1. Pressures below and across the BOP (with the test rams closed) are broadly the same now as they were prior to the Top Kill. This suggests that overall flow rates have not changed much, unless there is some unexplained mechanism in the well.
2. The pressure drop across the BOP has been relatively consistent, and it can be inferred that drillpipe is present and that flow through it has remained relatively unchanged.
3. The test rams would appear to be holding back pressure when they are closed, which suggests that there is at least some flow past the pipe rams.

CONFIDENTIAL

BP-HZN-217WDL00412074  
4/01/2008

TREX 005066.0001

TREX-005066.0001