



TrialGraphix

The Sperry-Sun flow-out sensor and the rig's flow line camera could not register returns going overboard. The Hitec flow-out sensor could, but data from the Hitec flow-out sensor sank with the rig.