

DECISIONS

2. Using long string casing instead of liner	No	
3. Not using the recommended number of centralizers	No	
4. Not circulating bottoms up prior to cement job	No	
5. Not waiting for foam stability test	Yes	
6. Not running cement bond log	No	
7. Using spacer made from lost circulation materials (LCM)	No	
8. Misinterpreting the Negative Pressure Test	Yes	
9. Displacing riser before setting cement plug	Maybe	
10. Displacing well to over 3,000 ft. below the mud line	Maybe	
11. Not installing additional physical barriers during temporary abandonment	Maybe	
12. Performing simultaneous operations during displacement	No	
13. Not automatically diverting overboard	Yes	

D-3282.n

TREX-23081.n

Sources: TREX-20001 (Bea/Gale Report, Pg 58 and 64);
Fns 216-222: TREX-20381, 20382, 20383, TREX-20380, TREX-20384, TREX-20395, TREX-06094, TREX-08173