

Summary of Opinions

- The rig crew failed to properly monitor the well on April 20, 2010 and allowed a kick to go unnoticed until it turned into a blowout.
- Even after recognizing that signs of a kick were present, the Transocean rig crew failed to shut in the well immediately.