

VBRs Closed and Sealed

- VBRs must have held seal until April 29 when casing shear ram closed
 - Erosion on underside of CSR supports flow through drill pipe
 - VBRs below the CSR sealed the annulus causing concentrated flow up drill pipe

