

There Was Not Enough "Force-From-Below" To Buckle the Drill Pipe Before the Annular Closed

