




BSR Did Not Fully Close Due to Drill Pipe Partially Outside Its Blades



Physical evidence shows the BSR was unable to fully close because the drill pipe was partially outside its blades