

Blowout Preventer

1. BOP FUNCTIONED ON APRIL 20
2. BOP COULD NOT SHUT IN WELL BECAUSE PIPE HAD BEEN FORCED OFF CENTER BY EXTREME FLOW
3. MAINTENANCE PLAYED NO ROLE IN BOP'S INABILITY TO SHUT IN WELL
4. BOP WAS CONFIGURED IN ACCORDANCE WITH INDUSTRY PRACTICE AT TIME OF INCIDENT