

Determine what Supplemental information Request
Discusses w/ Zighi W. W. double valve gaskets.

Also may run in Robert's oil

Page

Reliability

Impact of country w/ 3100 psi

Need to go to WSC, in which whether use Torgue-Turner
in which company did that, was pipe made up
in RIL on on bank in doubles

Interview w/ Mark Hall: Kent Cise, Tony Brack,
Brian Martin, Steve Robinson

Check on Discussion of Kinnick plans open state discussion

Well objective - MARK: DISCOVERY IN MIOCENE - 1X WELL

Failed by EXPANSION - SIMILAR TO ISABELLA. Nick: ?

25 miles away. Pressures overlaid

Pressure in sand lower than surrounding sands

Planned as a Key for FUTURE TRENCH

Secondary objectives: go to MSY - Primary thru O sands

DALG PROBLEMS caused 9 7/8" LINE

At 100 ft from hole section, DISCUSSION on length vs. length
TRENCH

Problems, recently w/ TRENCHES in TRENCH - water level

These problems & somewhat concern w/ TRENCH in Macdonald

DALG section. How to cut now w/ 14.5 to 14.3 ^{SURFACE} DUE TO LOSSES

Paul G. G. found 14.1 in one of the STANOS

DALG into STANOS w/ 14.3 SURFACE MW

Issues w/ onsite Pp prediction person. Frustration w/ HEC

HAFEX (cont)

TO INSTALL all of the Centrifuges. They required a Special Bonding Technique that caused EXTRA TIME.

Cement jobs went perfect.
Auto. fill float equipment. Weathered ~~the~~ equipment shoe. No Flapping, Float collar - double flapper.
~~from the~~ CSO with these reservoirs w/ floats open.
Doesn't seem like dispersion written but seemed to run.

Double Valve Weathered Float collar (auto fill) is standard & works okay. Common to need higher pressure because of Saccos taken in & collecting in shifting mechanism small portion.
~~the~~ 7" ~~in~~ structure & ~~up~~ ~~and~~ ~~made~~ ~~it~~ ~~up~~ ~~off~~ ~~stable~~ Torque. Turn should have been done in both places.

Reviewed Diagram of Float Collar - could not find actual picture

What about core Bore up? behind well & because of culture of Tech Center, we did not and would not
No 17

Cement job: 2 x 10 541 NBS & possibly better mixing this

Discussion about Form 505. Any issues or risk of or nitrogen ~~being~~ ~~over~~ & ~~citrus~~ ~~a~~ ~~problem~~?

Jobs went w/ a problem - flaps ~~being~~ ~~erectly~~ where they should

Hotie (can't)

Looking at this, well could have become unbalanced
or connected w/ BASE on ARROW

- Base on was part of the modelling. to reduce risk
of breaking in down

Tuesday 8:52p Vidrine called to discuss cent plug

- weight test or pressure test?

Hotie asked what was going on. Sent down

screened up in flow test & Vidrine said to
get it straightened out. Discussed that pressure
shouldn't be there. Don felt comfortable since
nothing came out of Kell Line

11:30p Mark received TEXT - phone # only. Called &

Talked to Jerry - asked about Kell on flow

Called Joan in 100 to see if True. confirmed
indicated 15 people missing

1st Part of Response. believes there was too much
emphasis on finding out what happened vs stopping
the flow. Discuss w/ Barbara. she directed him to
go thru the line.

Discussed the procedure.

Mark wrote procedure. To set plug 300' below
wellhead to allow room #1 look at below to set back
RING. Plan was to set surface plug in water. someones
P/Explanation wells.

Procedure written to negative test w/ string ARROW stuck 4
THEN RTH to 8367' & Repeat TEST. DISPLACE 500 to
500000 & then do a 2nd negative test. THEN set cent plug

HAFLE (cont's)

Team (Guide et al - Ops Team) wanted to go all the way to 8367' & DO TEST ONCE RATHER THAN TWICE. THIS DOES NOT MATCH AND MARK'S DECISION MADE THAT MMS DOESN'T NEED TO BE NOTIFIED. WHO MADE DECISION TO DO SINGLE NEG TEST @ 8367'? JOHN GUIDE MADE DECISION. MARK wanted to test seal array FIRST & THEN wellbore. Some discussion but JOHN GUIDE HAD TO ARGUE WITH. GREG WARE IN DISCUSSION BUT DON'T ARGUE W/JOHN.

Once decided by OPS, MARK goes back to OFFICE & called Bob to EXPLAIN PROCEDURE.

No detailed procedure provided because MARK does NOT know piping. Leave it to REG to decide details. EACH WSC LIKES TO DO IT DIFFERENTLY ANYWAY.

SPACER. DIDN'T KNOW WHY THEY put spacer in it. HAD IMPRESSION THAT KALUZA WASN'T REALLY CLEAR ON NEG TEST PROCEDURE

Who indicated MMS doesn't need to be called? JOHN GUIDE

~~After~~ MARK'S opinion on WHAT FLAREMS



5