


From: Guide, John
Sent: Thu Apr 15 17:31:38 2010
To: 'Paul.Johnson@deepwater.com'
Cc: Cocales, Brett W
Subject: Nile
Importance: Normal



Paul, I concur with not changing the annular elements prior to starting the Nile well. Bp accepts responsibility if both annulars were to fail and the stack had to be pulled to repair them. I also concur with waiting to change the drill line until after the Nile well is complete knowing there is a possibility it may have to be done during the well. Thanks.

John Guide
Rm: 02137A WL4
Office: 281-366-0531
Cell: 713-252-7918