

# What Bea Told BP Management

## WARNING

Look for problems

## WARNING

**Understand risk and stay vigilant.** It is critical to identify, mitigate, and minimize risk. A long period without a major accident does not mean that process safety risks have been properly mitigated and minimized.

2001

2002

2003

2005

TREX-20001 (Bea/Gale Report - Pgs v-vi, 17, 27-28);  
TREX-05950