



21:40

Mud begins to shoot from well; Chief Mate and Dynamic Positioning Officers (DPOs) observe from bridge

21:42

Damon Bankston advised by Bridge to move away from DWH

~21:41 – ~21:47

Drill crew sends flow to mud-gas separator; gas alarms are detected in engine control room

21:45 – 21:47

Drill crew calls Bridge: “we have a well control issue”

Bridge informs engine control room of a “well control situation.”

21:46

Gas arrives at surface

21:47

Multiple gas alarms sound

21:49

First explosion; second explosion

21:52

Mayday call made by DPO Fleytas from Bridge

~21:55

C. Pleasant activates the EDS. No power to BOP. EDS does not function.

Three EDS panels on the DWH

