


Chaisson's Notes

April 17, 2010



0700 Drill-Quip load didn't shear properly. Have to RIH: retrieve