

From: Guide, John
Sent: Thu Apr 15 17:31:38 2010
To: 'Paul.Johnson@deepwater.com'
Cc: Cocalles, Brett W
Subject: Nile
Importance: Normal

Paul, I concur with not changing the annular elements prior to starting the Nile well. Bp accepts responsibility if both annulars were to fail and the stack had to be pulled to repair them. I also concur with waiting to change the drill line until after the Nile well is complete knowing there is a possibility it may have to be done during the well. Thanks.

John Guide

Rm: 02137A WL4

Office: 281-366-0531

Cell: 713-252-7918



TREX-00680

BP-HZN-2179MDL00312134