

No Evidence of Hydrocarbons in the Annulus



October 7

Macondo 9 7/8" production casing was perforated at approximately 9180 ft. **No evidence of hydrocarbons in the annulus.**



October 13

BP recovered the production casing hanger and seal assembly from the MC-252 #1 wellhead. **Neither piece of equipment showed any signs of damage or erosion where annular flow would have caused serious erosion.**

