

BOP Timeline: Upper Annular Did Not Seal

- Slight increase in pressure at 21:42 shows upper annular closed but did not seal the well

