


BP ALARP REQUIREMENTS

BP Drilling and Well Operations Practice



GP10-00

3.3 Workplace Practices

- 3.3.1 All risks shall be managed to a level, which is as low as reasonably practicable. Risk management at the wellsite shall include the HSSE issues arising from the selection of resources, the design and operation of working systems, the control and disposal of waste and the delivery of services.