

Macondo System is Not Constant Over Time: Junk Shot Material in BOP and Drillpipe




Figure D-18