

Top Kill



Diagnostics Program

Can we kill the well?

Pumping

1. Mud Momentum Kill
2. Partial Bridge & Continue Mud Momentum Kill
3. Seal & Continue Mud Momentum Kill

Prerequisites Before Starting:

- Model Confirms We Can Kill Well
- 18" Casing Set on Relief Well
- Casing Shears re-closed
- Dispersant Approval
- Kit for Riser Cut
- Containment Tool Kit on Bottom
- HC Connector on DDII Stack

Is the Well Dead?

- ?Flow at Mudline/Not Dead
- ?Static Head
- ?Suction Head?

Pump Cement