

“Don’t Make It Worse” Top Risks



- Broach at the Seabed
 - 15% SF on Burst Disk
 - Pump Schedule
- Do Not Kill Well, More Oil Flowing
 - Erosion/Kink
- People, Pressure, SIMOPS
 - Operational Control
 - Organization
 - Communications
- Pressure Data Reliability
 - 5 Sources SS
 - Surface to SS Pressure Relationship – Finger Printing
- Impact Relief Well Success
- Public Perception of Failure