

144989.1.3

**From:** Sneddon, Iain (Aberdeen)  
**Sent:** Monday, May 24, 2010 9:54 PM  
**To:** Redd, Eddy (Houston); Olsen, Asbjorn (Stavanger)  
**Cc:** MacKay, John (Aberdeen); Blue, Mike (Houston); kiddg1@bp.com; Turlak, Rob (Houston)  
**Subject:** FW: Revised LMRP Removal Procedure DWH

**Attachments:** image003.gif; image002.gif; image001.wmz; image002.gif; image003.gif; MC252-1\_Sec-01\_LMRP Removal Procedures rev c.ZIP

Gents,  
For your information,  
Regards,  
Iain Sneddon

**From:** Sneddon, Iain (Aberdeen)  
**Sent:** Monday, May 24, 2010 9:54 PM  
**To:** Redd, Eddy (Houston); Olsen, Asbjorn (Stavanger)  
**Cc:** MacKay, John (Aberdeen); Blue, Mike (Houston); kiddg1@bp.com; Turlak, Rob (Houston)  
**Subject:** FW: Revised LMRP Removal Procedure DWH

**Attachments:** image003.gif; image002.gif; image001.wmz; image002.gif; image003.gif; MC252-1\_Sec-01\_LMRP Removal Procedures rev c.ZIP

Gents,  
For your information,  
Regards,  
Iain Sneddon

Team Leader (Technology Development – CAPM Project)

1.3 Section 9  
PDC crane to apply a load of 138 metric tonnes – would like to add a note for the drillers in the team – this includes a 50K lbs overpull in preparation for unlatching DEWH LMRP.

Other than that it looks OK.

Regards,

CONFIDENTIAL TRN-MDL-02469636

TREX-144989.0001