




Foam Cement Testing


 Not Sent to BP

 Sent to BP, but . . .

HALLIBURTON TESTING

2/12 

Foam Stability Test (16.8/17.6)
Crush Compressive Strength Test
("Slurry is settling will repeat")

2/16 


Foam Stability Test
(15.9/15.9) (2 hour conditioning time)
Crush Compressive Strength Test ("Hard on Bottom, Soft on Top")

 4/16

Foam Stability and Crush Compressive Strength Tests for .09 slurry Canceled

 4/13

Foam Stability Test on .08 slurry (15.7/15.1) (1.5 hour conditioning time) *weighing error
Crush Compressive Strength Test on .08 slurry

4/18 Cement Recommended
4/19 Cement Pumped
4/17 
Foam Stability Test on .08 slurry (15.0/15.0) (3 hours conditioning time)

FEB

MAR

APR

 3/8

2/16 Foam Stability test sent with wrong conditioning time
Crush Compressive Strength results sent without comments

4/1

Gagliano email with same attachment as 3/8

 4/18

4/13 Crush Compressive Strength Test result sent to BP, but
(1) 4/13 Foam stability test not sent
(2) BP not told that .09 slurry tests canceled
(3) BP not told of pending .08 foam stability test

 4/26

4/17 Foam Stability Test results sent to BP, but sent after the Incident

REPORTED TO BP