

BOP Timeline

Apr. 20

- ~21:40 – Mud overflowed onto the rig floor
- **21:42 – Annular closed**
 - Annular closed on tool joint shoulder which prevented the annular from sealing
 - EDS not yet activated

