


Seal Assembly Test

April 20, 2010, 1:00 – 3:00



Variable Bore Ram Closed

Drill Pipe

Fluid Pumped to Increase Pressure

Packer Placed Below Seal Assembly

No indication of fluid leak.