
## Negative Pressure Test

April 20, 2010, 15:56 – 19:55

Preparing for the Negative Pressure Test



- No MMS requirement or industry standard on how to conduct negative test
- Process safety test for integrity of the well
- One mile of mud in riser allowed for controlled underbalance of well

Source: TREX 0001, 02805