
Capping Stack - General Challenges



- Kinked riser removal
- Addressing internal debris
- Flex joint straightening and restraining
- Structural integrity of BOP stack and capping stack assembly
- Pressure rating of flex joint flange and flex joint
- Establishing a connection point

Source: TREX 144745, 009806 D23276