Criticism of Dr. Blunt's Report

- Failed to take into account uncertainties in
 - Original Oil in Place
 - Compressibility
- Failed to calibrate to known measurements
 - Collection rates
- Inconsistencies in his analysis

TREX-011654R.0009, .0013