Reasons Known by BP for Top Kill Failure

ORAL AND VIDEOTAPED DEPOSITION OF:



David Arnold Barnett

VOLUME 1

DECEMBER 14, 2012

1	Q. Okay. Did anyone in those conversations
2	on the rig express a view as to why they thought
3	the top kill may have failed?
4	A. As far as I recall, everyone was in
5	fairly close agreement that it was simply a
6	matter of the flow path was too big.

Source: Barnett TREX-100008.241