

- **21:49 – Explosions on the rig**
  - Rig power lost
  - Sperry-Sun real-time data transmission lost
  - MUX cables severed terminating BOP communications
  - EDS not yet activated

UPPER ANNULAR

UPPER VBR

MIDDLE VBR

