

**From:** DWH, SubSeaSup (Deepwater Horizon)  
**Sent:** Tuesday, February 16, 2010 5:43 PM  
**To:** Fry, Michael (Houston)  
**Subject:** RE: Transocean Horizon SEM

Mike,  
We don't have any. The Cajun has 5, the C.R. Lugas has 5 and the Sedco Express has 10.  
Could they get them and send me a quote for them and I'll either make out a new job for them or put them on the same job for the sem.

Thanks,

## Owen McWhorter

Sr. Subsea Supervisor  
Transocean Inc.  
Deepwater Horizon  
Phone: (713) 232-8262  
Fax: (713) 232-8268  
E-mail: [SubSeaSup.DWH@deepwater.com](mailto:SubSeaSup.DWH@deepwater.com)

This email and any files transmitted with it from Transocean Offshore Deepwater Drilling, Inc. are confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error please notify the sender.

---

**From:** Fry, Michael (Houston)  
**Sent:** Tuesday, February 16, 2010 11:02 AM  
**To:** DWH, SubSeaSup (Deepwater Horizon)  
**Subject:** RE: Transocean Horizon SEM

Battery part number is 2232368-01

Regards,

Michael Fry

Subsea Superintendent  
Transocean Technical Field Support  
Office 832-587-8516  
Cell 832-202-4011  
Fax 832-587-8555


---

**From:** DWH, SubSeaSup (Deepwater Horizon)  
**Sent:** Tuesday, February 16, 2010 7:27 AM  
**To:** Fry, Michael (Houston)  
**Subject:** RE: Transocean Horizon SEM

I'll have to check. You wouldn't happen to have the part number handy, would you ?

## Owen McWhorter

Sr. Subsea Supervisor  
Transocean Inc.  
Deepwater Horizon  
Phone: (713) 232-8262



TRN-MDL-00311104

TREX-03782

TDR013-008561

Fax: (713) 232-8268

E-mail: [SubSeaSup.DWH@deepwater.com](mailto:SubSeaSup.DWH@deepwater.com)

This email and any files transmitted with it from Transocean Offshore Deepwater Drilling, Inc. are confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error please notify the sender.

---

**From:** Fry, Michael (Houston)  
**Sent:** Monday, February 15, 2010 9:58 AM  
**To:** DWH, SubSeaSup (Deepwater Horizon)  
**Subject:** FW: Transocean Horizon SEM  
**Importance:** High

Owen,

Do you have any spare SEM batteries? We need some for your SEM at Cameron

Regards,

Michael Fry

Subsea Superintendent  
Transocean Technical Field Support  
Office 832-587-8516  
Cell 832-202-4011  
Fax 832-587-8555

---

**From:** Jarrett, Wallace S [mailto:Stan.Jarrett@c-a-m.com]  
**Sent:** Friday, February 12, 2010 8:51 AM  
**To:** Fry, Michael (Houston); Boughton, Geoff (Houston)  
**Subject:** FW: Transocean Horizon SEM  
**Importance:** High

Mike / Geoff,

Please see the comments below; as per Dana the rig was/or has batteries on that they are going to replace. Please advise...once this is resolved we can schedule a FAT witness.

*Stan Jarrett*  
 **CAMERON**

**Aftermarket Dept- (RGR)**

Direct: 713.423.8821  
Cell: 832.657.3717

"Broken, Dismantled, or needs Upgrading " Don't hesitate- Send it to Cameron Single RGR"

---

**From:** Mane, Abhay  
**Sent:** Friday, February 12, 2010 8:21 AM  
**To:** Jarrett, Wallace S  
**Cc:** Moore, James  
**Subject:** Transocean Horizon SEM

TRN-MDL-00311105

TDR013-008562

**Importance:** High

Stan:

The batteries on the Horizon SEM are not good and as per Dana, he never wanted to change the batteries. So for the FAT we need to ask the Customer to come up with some batteries or else we will use some from other projects, just for the FAT. But we need to ask the Customer whether they have spare on the rig.

Please advice.

**Thanks and Regards,**

**Abhay Mane**  
 **CAMERON**  
**Drilling Systems**  
**Production Control Coordinator**  
**6650 Bingle Road**  
**Houston TX 77092**  
**Tel: (713)-423-8308**  
**[abhay.mane@c-a-m.com](mailto:abhay.mane@c-a-m.com)**

~~~~~  
This email message is for the sole use of the intended recipient(s) and may contain confidential and privileged information of Cameron and its Operating Divisions. Any unauthorized use or disclosure is prohibited. If you are not the intended recipient, please contact the sender by reply email and delete and destroy all copies of the original message inclusive of any attachments.  
~~~~~

TRN-MDL-00311106

TDR013-008563