Safety Margin

- The Safety Margin of the Blind Shear Ram (BSR) was < 1.0
- BP should have increased the safety margin of the BSR, but made a conscious decision not to do so.

