## Reasons Known by BP for Top Kill Failure

ORAL AND VIDEOTAPED DEPOSITION OF:



## **David Arnold Barnett**

**VOLUME 1** 

**DECEMBER 14, 2012** 

11	Q. Okay. Did anyone in those conversations
12	on the rig express a view as to why they thought
13	the top kill may have failed?
13 14	A. As far as I recall, everyone was in
15	fairly close agreement that it was simply a
16	matter of the flow path was too big.

Source: Barnett TREX-100008.241