
Phase 2 Expert Reports of Dr. Robert Bea

Gulf of Mexico.

HORIZON



1. BP Management knowingly ignored required Process Safety Management mitigations for blowout source control in deepwater exploration wells drilled by contractorowned Mobile Offshore Drilling Units in the

BP Management's Process Safety
Management blowout source control
failures resulted from a disregard of the risk
of loss of primary containment and
uncontrolled flow of oil and gas from the
Macondo well.