D23934.1

D23934

Capping Stack Activities Timeline April 27: May 14: June 5: June 23: July 5: July 7: Well Capping Peer assist Government Provide update to **Unified Command** First version of Technical Assurance meeting review of government on approves installation Organizational connection connection concepts procedure Report Issued Activities concepts June 10: Government review of flex joint overshot June 30: 9 Replacement pressure sensor installed **Capping Stack** Activity May 19: 1 June 2: 1 June 28: 1 July 2: 3 ram capping Capping stack Integration testing with Capping stack stack proposed valves changed to transition spool completed offshore fail open June 16: May 1: May 18: July 3: Transition spool First version of transition spool and Commencement of flex joint Flex joint restraints Transition concept proposed mule shoe manufactured restraints manufacturing completed Spool June 7-13: Activity May 12: May 21: June 27: Transition spool Final transition spool First mule Flex joint overshot shoe designed proposed guidance trials testing completed June 3: June 16: July 7: July 10-12: Riser cut Completed HAZID Restraints installed Capping stack of bolt removal and transition Installation spool installed **Activities** May 2: June 24-29: July 15: 9 June 13: Completed HAZID Subsea bolting trial Well shut in Installation for riser removal tools tested APR

Source: TREX 144342, 144343, 144341, 144629, 141074, 143043, 9675, 145308, 142744, 143049, 143042, 143047, 144347, 142626, 142733, 142913,

142406, 142807, 145037, 145005, 120151, 143054, 143055, 142743, 144745, Smith Dep. at 23:16-24:19, 496:6-11