

# 1. Weatherford test results relied on by Drs. Zimmerman and Blunt are not reliable and are underpredictive

## a. Tested cores not representative

1. Low number of suitable samples relative to the size of the reservoir.
2. Evidence of sample damage from drilling process.
3. Well logs show that core properties were not representative of average reservoir properties.