

Macondo System is Not Constant Over Time: Drillpipe Detached



Figure D-12.
Drill Pipe Erosion
– Test Ram




Figure 12. Position of Drill Pipe in the Well After Shut-in

Note: Not to scale