

9474

Exhibit No. _____
Worldwide Court
Reporters, Inc.

From: Hill, Trevor
Sent: Sun May 16 20:44:48 2010
To: Saidi, Farah
Subject: RE: Update
Importance: Normal

Thanks... understood...

From: Saidi, Farah
Sent: 16 May 2010 21:14
To: Hill, Trevor
Subject: RE: Update

We are still depressurizing the system. Since the rates are confidential and I was told by Mike Brown not to write anything about it, he advises to call Paul Tooms. It seems the system is working which is encouraging and the team is already working on the second version of the tool based on learning from this tool.

Regards,

Farah Saidi

BP

Office 281-366-5746

Cell 832-978-4121

<< OLE Object: Picture (Metafile) >>

From: Hill, Trevor
Sent: Sunday, May 16, 2010 3:08 PM
To: Saidi, Farah
Subject: Update

Farah

I'd be grateful for any early indications of how the tube is working, whether it is picking up most of the oil, what the measured rate is through the process etc...

Regards

Trevor

Trevor Hill

E&P Engineering Technical Authority - Flow Assurance

+44 (0)7879 486974

BP Exploration Operating Co Ltd

Registered office: Chertsey Road, Sunbury on Thames, Middlesex, TW16 7BP, United Kingdom

Registered in England and Wales, number 305943

[Flow Assurance BP Intranet Site](#)

[Flow Assurance in BP Connect](#)

CONFIDENTIAL

BP-HZN-2179MDL07037064

BPD568-017069

TREX 009474.0001