From: Morel, Brian P

Sent: Tue Mar 23 12:04:27 2010

To: Hafle, Mark E

Subject: RE: Open hole lot?

Importance: Normal

I do not believe we will make TD at 15100' with the current PP team onboard using 13.7 as a max LOT. They are going to be way too cautious. I guess I don't get how they say we can have a 12.9 ppg with pore pressure but don't believe the 14.7 LOT. Maybe we set our casing into a higher pressured regime which exists at that shale and below??? Stranger things have occurred.

Trip for GeoTap if we can't get them onboard with the higher LOT, cause no chance of pushing casing point without it or understanding that pp is lower than expected.

----Original Message----From: Hafle, Mark E

Sent: Tuesday, March 23, 2010 7:00 AM

To: Morel, Brian P

Subject: RE: Open hole lot?

Worth asking to do an openhole FIT to say 14.5

Also worth tripping for GeoTap?

----Original Message----

From: Morel, Brian P

Sent: Monday, March 22, 2010 9:14 PM

To: Hafle, Mark E Subject: Open hole lot?

Think I should push guide again, sonic isn't working well would be nice to know if we can trust that high lot value.

Brian Morel

BP Drilling Engineer

713-303-0120 cell

281-366-1706 office

BlackBerry Wireless Device

