From: Vidrine, Don J

Sent: Tue Apr 20 12:23:14 2010

To: Tippetts, Brad

Subject: FW: Updated Procedure

Importance: Normal

Attachments: Macondo\_Drilling\_Production\_Interval BP01\_rev2.ZIP

From: Morel, Brian P

Sent: Thursday, April 15, 2010 11:38 PM

To: Sepulvado, Ronald W; Vidrine, Don J; Kaluza, Robert; Lambert, Lee; Guide, John; Hafle, Mark E; Cocales,

Brett W; Walz, Gregory S

Cc: Lindner, Leo T (MI DRILLING FLUIDS, INC)

Subject: Updated Procedure

Attached is the updated procedure based on our current plan forward. If anything changes I will update and send the next revision out. We are still waiting for approval of the departure to set our surface plug 3000' BML. If we do not get this approved, the displacement/plug will be completed shallower after running the LDS (basic details of this change are included in this procedure). Please let me know if you have any questions or suggestions.

A detailed cement procedure should be available from Jesse sometime tomorrow.

Thank You, Brian Morel