


# Crew Failed to Conduct EDS Drills at Macondo

IADC

BP-HZN-217WDL00251100



**The IADC Daily Drilling Reports for the DWH at Macondo  
(January-April 2010)**